K32 Dual Pilot Fan Clutch

HORTON

Replacement Fan Clutch Repair Kits for KYSOR® K26RA, K30RA and K32RA

Benefit from Horton's industry-leading customer service and quality, even if you are running its competitors' fan drives in your fleet.

- **Dual pilot for reduced inventory and complete application coverage**
- **Two-piece liner design for quick repairs**
- **Superior liner material for longer life and reliability**

Count on Horton to not only provide the reliable, durable products you need, but to deliver them on time

ENGINEERED FOR:

K32 Replacement Fan Drive Repair Kits

Rear-Air Fan Clutch

Horton # 9908504
Replaces #
1090-09650-01
1090-09750-01
8801X
8801N
8905N
8901N
9908501
9908503

Rear-Air Major Kit

Horton # 9908408
Replaces #
1033-40600-02
8800SKL

Rear-Air Seal Kit

Horton # 9908409
Replaces #
1033-08233-01
8500SK



Lining Kit

(fit's both rear-air and front-air fan clutches)

Horton # 9908407
Replaces #
1033-40600-01
8800L

Hub Bearing Kits

Horton # 9908300
Replaces #
1033-07781-01
8581-01

Horton # 9908301
Replaces #
1033-07782-01
8582-01

Horton # 9908302
Replaces #
1033-07782-02
8582-02

Horton # 9908303
Replaces #
1033-07782-03
8582-03

Horton # 9908304
Replaces #
1033-07782-04
8582-04

Visit catalog.hortonww.com
to view full list of part number cross references!

Committed to Your Ideal Airflow Solution
Horton® is the premium provider of engine cooling solutions worldwide. Our culture of innovation delivers high-performance products that last and services that help you meet your commitments. Trust Horton to help your products last longer, run quieter and consume less fuel.

Horton is IATF 16949, ISO 14001 and ISO 9001 certified.

© 2022 Horton Holding, Inc. All rights reserved.
Form #23324-D-1122 EN

www.hortonww.com