

Dorman Engineered Solutions to Known OE Problems



OE PROBLEM:

Original design is constructed out of black plastic and relies on fluid level indicator ports to gage fluid levels. These ports are often the source for fluid leaks.



Changed tank construction material to a clear plastic that improves reading fluid levels eliminating the need for fluid level indicator ports, lessening the risk for fluid leaks



PRESSURIZED COOLANT RESERVOIR

- Comes with reservoir cap
- Improved design removing OE failure points
- Direct replacement for a proper fit every time
- Quality tested to ensure trouble-free installation and performance

603-5103

International 2013-01

OE Numbers:

2508700C91, 2508700C92
2508700C93, 3565217F93



OE PROBLEM:

Original design is constructed out of black plastic, making it difficult to determine fluid level.



Changed tank construction material to a clear plastic that improves reading fluid levels without the need of opening reservoir cap.



PRESSURIZED COOLANT RESERVOIR

- Direct replacement for a proper fit every time
- Comes with reservoir cap
- Level sensor included (where applicable)
- Quality tested to ensure trouble-free installation and performance

603-5107

International 2011-01

OE Numbers:

2587216C1, 2591802C2

Dorman Engineered Solutions to Known OE Problems



OE PROBLEM:

The OE cap that connects to the internal filter gets locked into place after use and is often broken during filter replacement. If the OE cap breaks, installer is forced to purchase a full reservoir.



OE FIX

Dorman OE fix adds a hex-head to the base of the hose port on this cap to allow for easy removal and filter replacement.



603-5206

Freightliner 2014-08

OE Numbers:

A1414796003,
A1419133000

POWER STEERING RESERVOIR

- Included reservoir cap and dipstick (where applicable)
- Direct replacement for a proper fit every time
- Weather-resistant
- Rigorous quality control measures have been undertaken to ensure that this part conforms to product standards



OE PROBLEM:

Due to the part's placement in the vehicle, the original design allowed for debris to enter under cap, damaging the internal gasket.



OE FIX

Replaced the OE designed cap with an improved threaded cap, which provides a better seal to keep road debris from entering the reservoir.



603-5106

International 2016-12,
International 2010-02

OE Numbers:

3558153C93, 3558153C94,
3558303C4, 3569593C93,
4043516C91

POWER STEERING RESERVOIR

- Included reservoir cap, dipstick and filter (where applicable)
- Direct replacement for a proper fit every time
- Weather-resistant
- Rigorous quality control measures have been undertaken to ensure that this part conforms to product standards



RESERVOIR TOP APPLICATIONS



MAKE	MODELS	YEARS	DORMAN #	OE #	NOTE
HEAVY DUTY POWER STEERING RESERVOIR					
Freightliner	M2	2014-08	603-5206	A1414796003, A1419133000	
International	4300, 4400	2016-12	603-5106	3558153C93/C94, 3558303C4, 3569593C93, 4043516C91	
International	Various	2010-02	603-5106	3558153C93/C94, 3558303C4, 3569593C93, 4043516C91	
HEAVY DUTY COOLANT RESERVOIR					
Chevrolet	Various	2009-03	603-5601	15161670	Pressurized
Freightliner	M2, 108SD, 114SD	2019-10	603-5207	A0528531000/001/002	Pressurized
Freightliner	Various	2019-08	603-5203	A0525263005/005/007, A0533118000	Pressurized
Freightliner	Various	2018-05	603-5202	0521178000, 0523195000/001/002, Z0530740000/001	Pressurized
Freightliner	Sprinter, Classic, Century	2016-09	603-5209	0516364000, EX03AC00019SP	Pressurized
Freightliner	Columbia, Coronado	2015-10	603-5201	0520529000, 0523045000/001	Pressurized
Freightliner	Classic/XL, FLD132/112/120/120SD/132	2011-01	603-5219	A0519234000, A0523574000	Pressurized
Freightliner	Columbia, Century Class	2007-01	603-5201	0520529000, 0523045000/001	Pressurized
Freightliner	FL, FLC, FLD	2002-95	603-5209	0516364000, EX03AC00019SP	Pressurized
GMC	Various	2009-03	603-5601	15161670	Pressurized
IC Corp.	Various	2018-06	603-5104	2591625C92, 2599039C91, 2602872C91, 2602943C91, 3829605F91/F92	Pressurized
IC Bus	Various	2005-02	603-5110	2602935C91, 4C4Z8B379A	Pressurized
International	ProStar	2020-07	603-5105	2591620C91, 3599401F91/F92/F93/F94/F95	Pressurized
International	9900i	2018-03	603-5105	2591620C91, 3599401F91/F92/F93/F94/F95	Pressurized
International	Various	2018-06	603-5104	2591625C92, 2599039C91, 2602872C91, 2602943C91, 3829605F91/F92	Pressurized
International	Various	2013-01	603-5103	2508700C91/C92/C93, 3565217F91/F92/F93	Pressurized
International	7300/400/500, CXT, MXT	2011-01	603-5107	2587216C1, 2591802C1	Pressurized
International	5900	2009-03	603-5105	2591620C91, 3599401F91/F92/F93/F94/F95	Pressurized
International	7600	2007-03	603-5131	2508124C1/4C2/4C3	Pressurized
International	7700	2007-05	603-5131	2508124C1/4C2/4C3	Pressurized
International	Various	2005-02	603-5110	2039390C3, 2587324C1, 2602935C91, 3578833C3, 3829604F91/F92, 4C4Z8B379A, BC4Z8A080A	Pressurized
International	3800, 4700/LP/LPX, 4800, 4900	2002-95	603-5101	1619114C1/4C2/4C3/4C4/4C5, 2002105C2/5C3, 5C4Z8A080AA	Pressurized
Isuzu	Various	2008-05	603-5601	15161670	Pressurized
Kenworth	Various	2022-19	603-5403	T1673008/009, N5346001	Pressurized
Kenworth	Various	2017-08	603-5403	T1673008, N5346001	Pressurized



RESERVOIR TOP APPLICATIONS



MAKE	MODELS	YEARS	DORMAN #	OE #	NOTE
HEAVY DUTY COOLANT RESERVOIR (cont.)					
Mack	Various	2021-08	603-5505	21074555, 21314361, 21513975, 21846997, 23911823	Pressurized
Mack	GU7, GU8	2008	603-5502	25174629, 76MF520M	Pressurized
Mack	CV	2007-02	603-5502	25174629, 76MF520M	Pressurized
Peterbilt	Various	2022-08	603-5403	T1673008/009, N5346001	Pressurized
Sterling Truck	Various	2004-99	603-5211	24224219, A0523573000	Pressurized
Thomas Bus	C2	2010-05	603-5202	Z0530740000/001	Pressurized
Volvo	Various	2018-08	603-5505	20881601/604, 20900982, 20968795/839, 21000194, 21038101, 21067134, 21074569, 21314359/361, 21513979, 21846995, 22061288/290, 22564835/837, 23059017	Pressurized
Volvo	VN, VNL, VNM	2007-04	603-5504	1674922, 20461002, 20505819, 20519037/039, 8140024	Pressurized
Volvo	VN, VNL, VNM	2003-98	603-5507	1674916/922, 20517007, 21399626, 8140024, 8149506	Pressurized
Volvo	WG	2000-96	603-5510	3966106/107, 212013201/202, 212073201/202	Pressurized
Volvo	WI	1998-90	603-5510	3966106/107, 212013201/202, 212073201/202	Pressurized
Volvo	WC, WH, WX	1994-90	603-5510	3966106	Pressurized
Chevrolet	Various	1998-90	603-5604	15688604	Non-Pressurized
GMC	Various	1998-90	603-5604	15688604	Non-Pressurized
Mack	GU7, GU8	2008	603-5501	25133601	Non-Pressurized
HEAVY DUTY WINDSHIELD WASHER FLUID RESERVOIR					
Kenworth	T680, T880	2019-13	603-5402	N5355001, P6615001	
Kenworth	Various	2019-95	603-5401	K11420/446, R861001/004/011	
Peterbilt	Various	2019-00	603-5402	N5355001, P6615001	
Peterbilt	357, 377, 379	2007-89	603-5404	R866001	
Peterbilt	375	1999-89	603-5404	R866001	